


DATE: December 1990

TO: All Exec 90 Builders

EXEC 90 ADVISORY BULLETIN - 01

According to our records, your aligner blocks may have been machined incorrectly. Easy identification can be made as follows: Looking at the three tapped holes in the end of the block, the middle hole should be offset approximately 1/8" to one side.

CORRECT



If the middle hole is centered between the other two, both blocks must be returned to RotorWay for exchange.

INCORRECT

