



7150 W. Erie Street Chandler, AZ 85226 USA
Phone: 480.961.1001; Fax: 480.961.1514
www.rotorway.com

Pride in Craftsmanship since 1967

4-28-2008

ALL TALON AIRCRAFT KITS SHIPPED FROM OCTOBER – MARCH 2008

Inspection of part #E15-9021 throttle shaft weldment is required for security of the welded on bushing. This part is located in the, "F" box. RotorWay suggests that you return this part for replacement. Please contact RotorWay parts department for shipping instructions if needed.

