



4141 W. CHANDLER BOULEVARD • CHANDLER, AZ 85226 • USA  
PHONE (602) 961-1001 FAX (602) 961-1514

May 12, 1995

**TO ALL EXEC AND EXEC 90 OWNERS**

**EXEC/EXEC 90 ADVISORY BULLETIN A-24**

History: If a fuel line was to break or pull loose during a hard landing, rollover, or other incident, an extremely serious fuel spill could result.

Action: The addition of the inertia switch system is recommended for all Exec and Exec 90 helicopters. The system will automatically turn off the fuel pumps in the event of a hard impact, reducing the possibility of a fuel spill. This was originally developed for use with fuel injection on the Exec 162F, and also works well for carbureted engines.

The Inertia Switch Kit (part number E25-4780) consists of two switches, a mounting bracket, and mounting hardware. It can be easily wired in to your helicopter's existing wiring harness. Please contact our parts department at (602) 961-1001 or fax (602) 961-1514.