



300 South 25th Ave. Phoenix, Arizona 85009 / 602-278-8899
FAX 602-278-7657

DATE March 21, 1991

TO ALL EXEC 90 BUILDERS

EXEC 90 MANDATORY COMPLIANCE BULLETIN M-02

THIS BULLETIN IS MANDATORY AND MUST BE COMPLIED WITH

Installation of tubes E10-3145 and E10-3155 is mandatory on Exec 90 airframes. These formed 1 inch diameter tubes are designed to improve the stress distribution on several sections of the airframe.

Refer to enclosed drawing and See-Do photos for step by step instruction.

